

Demo Door Co.

345 West Industrial Road

Anytown, USA 58466

p:(555) 555-5555 | f:(555) 444-4444

service@demodoorco.com

**Building - Follow-Up Work**

Report Date Apr 01, 2015 12:54 MDT

This report summarizes the required and suggested follow-up work for all of the building's door systems based on the most recent SafedoorPM inspections.

Customer:	Darrien Welding & Grinding	Building:	Main Fab Shop
Address	9503 - 45 Avenue, Tucson, AZ, US - 84596		
Contact 1:	John Anderson	Contact 2:	Rhonda Paige
Phone:	805-555-4588	Phone:	805-652-3655
Email:	john@dbf.com	Email:	rhonda@dbf.com

REQUIRED FOLLOW-UP WORK FOR SAFEDOORPM COMPLIANCE

DOOR ID	DOOR NOTES	INSPECTION	GRADE	INSPECTION ELEMENT	INSPECTION NOTES	PHOTO
0001722	Shipping Door 1	Feb 24, 2015	Fail	Cables, cable anchors, bottom brackets	[2015-02-24 14:45] FW: Cables twisting	Yes (1)
0001722	Shipping Door 1	Feb 24, 2015	Fail	Shaft, couplers, drums	[2015-02-24 14:50] FW: LHS drum worn D850-132	Yes (1)
0001722	Shipping Door 1	Feb 24, 2015	Fail	Door level, balance	[2015-02-24 14:47] FW: Door heavy	
0001723	Shipping Door 2	Feb 24, 2015	Fail	Door level, balance	[2015-02-24 15:09] FW: Door heavy	
0001723	Shipping Door 2	Feb 24, 2015	Fail	Door safety labeling	[2015-04-01 12:53] FW: Needs warning labels	
0001724	Shipping Door 3	Feb 24, 2015	Fail	Torsion springs	[2015-04-01 12:52] FW: Door heavy.	

Demo Door Co.

345 West Industrial Road

Anytown, USA 58466

p:(555) 555-5555 | f:(555) 444-4444



service@demodoorco.com

**Building - Follow-Up Work**

Report Date Apr 01, 2015 12:54 MDT

This report summarizes the required and suggested follow-up work for all of the building's door systems based on the most recent SafedoorPM inspections.

REQUIRED WORK PHOTOS

REQUIRED WORK PHOTOS							
							
0001722	Cables, cable anchors, bottom brackets	0001722	Shaft, couplers, drums				

SUGGESTED FOLLOW-UP WORK

DOOR ID	DOOR NOTES	INSPECTION	GRADE	INSPECTION ELEMENT	INSPECTION NOTES	PHOTO
0001722	Shipping Door 1	Feb 24, 2015	Pass	Sections, joints, gaskets	[2015-02-24 14:46] FW: Bottom panel creased	Yes (1)
0001723	Shipping Door 2	Feb 24, 2015	Pass	Weatherstrip, U-rubber, top flap	[2015-02-24 15:10] FW: RHS weatherstripping torn	Yes (1)
0001724	Shipping Door 3	Feb 24, 2015	Pass	Sections, joints, gaskets	[2015-02-24 15:22] FW: Bottom section creased	Yes (1)
0001724	Shipping Door 3	Feb 24, 2015	Pass	Weatherstrip, U-rubber, top flap	[2015-02-24 15:26] FW: LHS weatherstripping damaged	Yes (1)

Demo Door Co.

345 West Industrial Road

Anytown, USA 58466

p:(555) 555-5555 | f:(555) 444-4444

service@demodoorco.com







Building - Follow-Up Work

Report Date Apr 01, 2015 12:54 MDT

This report summarizes the required and suggested follow-up work for all of the building's door systems based on the most recent SafedoorPM inspections.

SUGGESTED WORK PHOTOS

							
0001722	Sections, joints, gaskets						
							
0001723	Weatherstrip, U-rubber, top flap						
							
0001724	Sections, joints, gaskets	0001724	Weatherstrip, U-rubber, top flap				